
	<b>CHANGES</b>	
	<b>Gravostyle 8 Build 5 to Build 5c</b>	

## Main Changes

### **Drivers Machines :**

<i>LSolution</i>	7.25-3
<i>GT Smartstream</i>	4.06
<i>GravoTech laser</i>	4.12-2

### **Firmwares Machines :**

<i>Sirius :</i>	2.39
<i>UC_K2000 Méca :</i>	4.33
<i>UC_K2000 Laser :</i>	4.44
<i>IM4E :</i>	2.26
<i>FSeries Galvo</i>	1.050
<i>MajFirmware</i>	1.07

### **Date :**

*Exe :* 15 april 2019

### **Drivers Camera Print & Cut:**

<i>32 Bits :</i>	<i>uEye32_49100_WHQL.exe</i>
<i>64 Bits</i>	<i>uEye64_49100_WHQL.exe</i>

### **Driver Cle HASP :**

*Version 7.90*

### **Version JAR :**

*Version 2.2*

## Changes



### **Firmware :**

- Update firmware UC\_K2000 for laser machine : 4.44 instead of 4.33

### **Polices / Fonts / Symboles :**

- JANSON 1L and ENGLISH SCRIPT fonts added

### **Driver :**

- Update LSolution driver to 7.25-3 instead of 7.21-3

### **Langues / Documentations :**

- Update translations : FR, IT, DK, FL, HE, BR, PO, SP
- Update help files : IT, JP, US, RU, TU

### **Bugs fixed :**

- Layout wizard / Assistant Matière et Gravure en bague intérieure : problème d'origine